

Customer	:	CU-DAR001	Dart Helicopters Services	Drawing Name	:	VERTICAL REFERENCE WINDOW		
Job Number	:	42372						
Estimate Number	:	13616						
P.O. Number	:				Part Number	:	D350567117	
This Issue	:	01/10/2008	S.O. No. :		Drawing Number	:	N/A UNDER REVIEW	
Prsht Rev.	:	NC			Project Number	:	N/A	
First Issue	:	//	Type	:	Drawing Revision	:	N/A	
Previous Run	:	42371			Material	:		
Written By	:				Due Date	:	08/10/2008	Qty: 1 Um: Each
Checked & Approved By	:	<u>CMF 08-10-01</u>						
Comment	:	Est Rev:A 08.09.30 new issue EC verified by: DD						



1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the work.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete them.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress to ensure that the objectives are being met.

5. The final step is to evaluate the results of the project. This involves assessing the outcomes against the objectives and identifying any areas for improvement or further action.

1.0 DC  DOCUMENT CONTROL

Photocopy bluefile and create labels and DT8439 Template per PPP D350-567-112 CHG003

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------

Comment: PACKAGING RESOURCE #1
Pick Packing Kit

~~***ENSURE DT 8439 TEMPLATE IS INCLUDED***~~

3.0	42372A	REPLACEMENT WINDOW KIT
-----	--------	------------------------

Comment: Sub-Component REPLACEMENT WINDOW KIT
1 x D350-567-113 Batch 42372A

4.0 42372B 1.5 25 350/355 FLOOR WINDOW KIT (INTERIOR)

Comment: Sub-Component 350/355 FLOOR WINDOW KIT (INTERIOR)

5.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
-----	-----	------------------------------------

Comment: INSPECT 100% KITS FOR COMPLETENESS

6.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------

Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-567-111

Location: 23 Kelf A

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 01/10/2008 11:22:06 AM
User: Melanie Fauteux

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: VERTICAL REFERENCE WINDOW

Job Number: 42372

Part Number: D350567117

Job Number:



Seq. #:

Machine Or Operation:

Description :

7.0

QC21

FINAL INSPECTION/W/O RELEASE



09/04/08

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 09-04-07

POSITIVE RECALL
EFFECTIVE 08/02 AUTH LL
RELEASED 09-04-07 DATE LL

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries